



**Figure #1 DRAFT Rattlesnake Greenbelt  
Existing Conditions**

February 2019



FIGURE 3: Key features at the Rattlesnake Dam as identified in the 2018 MacDonald survey

Rattlesnake Dam – Historic and Cultural Resource Survey and Evaluation - 2018



**Figure 8 - Feature Location Key**

- |                            |                            |
|----------------------------|----------------------------|
| 1. Main Dam Structure      | 6. Abandoned Head gate     |
| 2. East Screening Facility | 7. Exposed Twin Pipe Stubs |
| 3. West Screening Facility | 8. Garage                  |
| 4. Elevated Cistern        | 9. Main Reservoir          |
| 5. Chlorinating Building   | 10. North Head Gate        |